



# VEHICLE INSPECTION REPORT

**SV53LNC**

## Volkswagen Polo 1.4 Twist 3dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
4

### Details

Reg. date	26/09/2003	Keys	2	CAP Clean	£780.00
Year	2003	Service history	Yes	CAP Average	£380.00
Mileage	54,924 Miles Warranted	Service documents	Service Book	CAP Below	£200.00
Fuel Type	Petrol	Number of stamps	13	Gearbox	AUTOMATIC
Colour	GREEN	Last service date	18/01/2025	Gears	4
VIN	WVWZZZ9NZ4Y056311	Last service miles	53,352	Doors	3
Body Style	Hatchback	MOT Due	22/01/2026		

Last Service - 18.01.2025 at 53352 miles (13 services)

### Tyres

NSF	HIFLY	3.0mm
NSR	BUDGET	2.0mm
OSF	BUDGET	3.0mm
OSR	BUDGET	3.0mm
Spare		

## Features


- PAS
- Electric door mirrors
- Front head restraints
- 3x3 point rear seat belts
- Remote central locking
- Rear wiper
- Air conditioning
- Height adjustable drivers seat
- Drivers airbag
- Cloth seat trim
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Alloy wheels
- Body coloured bumpers
- Front electric windows
- Metallic Paint
- Central locking

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Scratched  
Over 100mm Thru Paint





3: Wing nsf  
Chipped  
Multiple Chips



4: Wheel nsf  
Scratched  
Over 50mm



5: Door nsf  
Chipped  
Multiple Chips



6: Qtr Panel nsr  
Dented  
With Paint Damage



7: Wheel nsr  
Scratched  
Over 50mm



8: Bumper Rear  
Scratched  
Over 100mm Thru Paint

No Image



9: Boot Lid  
Scratched  
Over 25mm Not Thru Paint

10: Qtr Panel osr  
Dented  
With Paint Damage



11: Wheel osr  
Scratched  
Over 50mm



12: Door osf  
Dented  
With Paint Damage



13: Wing osf  
Chipped  
1 To 5



14: Wheel osf  
Scratched  
Over 50mm





15: Screen Front  
Chipped  
UpTo 10mm

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK