



46 Brampton Road
Eastbourne
BN22 9BN

01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

LC12NPU

Mercedes-Benz B Class B180 CDI BlueEFFICIENCY SE 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC



Details

Reg. date	28/06/2012	Colour	SILVER	MOT Due	17/09/2025
Year	2012	VIN	WDD2462002J074347	CAP Clean	£2,325.00
Mileage	79,430 Miles Warranted	Body Style	MPV	CAP Average	£1,900.00
Fuel Type	Diesel	Keys	1	CAP Below	£1,450.00

£65 ADDITIONAL FEE. Brake service warning display


Tyres

NSF	GOODYEAR	5.0mm
NSR	GOODYEAR	5.0mm
OSF	GOODYEAR	5.0mm
OSR	GOODYEAR	5.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- ABS
- Isofix child seat anchor points
- Central locking
- Front parking sensor
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- Curtain airbags
- Passenger airbag
- Remote central locking
- PAS
- Digital radio
- Air conditioning
- Front head restraints
- Metallic Paint
- Drivers airbag
- Rear airbags
- Cloth seat trim
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- 3x3 point rear seat belts
- ESP
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bumper Front
Scratched
Over 100mm Thru Paint



2: Bonnet
Chipped
1 To 5



3: Wheel nsf
Scratched
Over 50mm



4: Door nsf
Dented
Between 10mm + 30mm



5: Door nsr
Dented
Between 10mm + 30mm



6: Wheel nsr
Scratched
Up To 50mm



7: Bumper Rear
Scratched
25 to 100mm Thru Paint



8: Wheel osr
Scratched
Up To 50mm



9: Door osf
Chipped
Edge Chip



10: Wheel osf
Scratched
Up To 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	Fault	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK