



VEHICLE INSPECTION REPORT

GP59EKB

Volkswagen Polo 1.2 60 S 3dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
5

Details

Reg. date	11/02/2010	Body Style	Hatchback	CAP Below	£425.00
Year	2010	Keys	2	Gearbox	MANUAL
Mileage	105,428 Miles Warranted	Service history	None	Gears	5
Fuel Type	Petrol	MOT Due	11/02/2026	Doors	3
Colour	SILVER	CAP Clean	£1,225.00		
VIN	WVWZZZ6RZAY153348	CAP Average	£860.00		

NO SERVICE HISTORY Front suspension knocking

Tyres

NSF	BUDGET	5.0mm
NSR	DOUBLESTAR	5.0mm
OSF	BUDGET	5.0mm
OSR	DOUBLESTAR	5.0mm
Spare		

Features


- PAS
- Folding rear seats
- Rear headrests
- Drivers airbag
- Central locking
- Rear wiper
- Front electric windows
- Metallic Paint
- ESP
- Remote central locking
- Radio/CD
- Front head restraints
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Body coloured bumpers
- Height adjustable drivers seat
- ABS
- Side airbags
- Steel wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Roof
Chipped
Edge Chip



4: Door nsf
Dented
Over 30% Of Panel



5: Qtr Panel nsr
Dented
With Paint Damage



6: Bumper Rear
Dented
With Paint Damage



7: Qtr Panel osr
Dented
Over 30mm



8: Door osf
Dented
With Paint Damage



9: Wing of
Chipped
1 To 5

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK