



VEHICLE INSPECTION REPORT

HG70ATZ

Renault Clio 1.0 TCe 100 Iconic 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	13/11/2020	Keys	2	CAP Clean	£8,375.00
Year	2020	Service history	Yes	CAP Average	£7,400.00
Mileage	40,824 Miles Warranted	Service documents	Service Book	CAP Below	£6,400.00
Fuel Type	Petrol	Number of stamps	2	Gearbox	MANUAL
Colour	BLUE	Last service date	23/10/2024	Gears	5
VIN	VF1RJA00064960655	Last service miles	35,170	Doors	5
Body Style	Hatchback	MOT Due	12/11/2025		

£65 ADDITIONAL FEE.

Last service 23/10/2024 at 35,170 miles- 2 main dealer services Rear parking sensors faulty

Tyres

NSF	BUDGET	6.0mm
NSR	BRIDGESTONE	5.0mm
OSF	BUDGET	6.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Navigation system
- Digital radio
- Air conditioning
- Height adjustable drivers seat
- ABS
- Side airbags
- Alloy wheels
- PAS
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint




3: Wing nsf
Chipped
1 To 5



4: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



5: Door nsf
Chipped
Edge Chip



6: Door nsr
Scratched
Over 25mm Thru Paint



7: Qtr Panel osr
Scratched
Over 25mm Thru Paint



8: Door osr
Scratched
Over 25mm Thru Paint



9: Door osf
Chipped
Multiple Chips



10: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK