



# VEHICLE INSPECTION REPORT

**GN65XFE**

## Nissan Note 1.2 Acenta 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	01/09/2015	Keys	2	CAP Clean	£2,375.00
Year	2015	Service history	Yes	CAP Average	£1,925.00
Mileage	69,809 Miles Warranted	Service documents	Service Book	CAP Below	£1,475.00
Fuel Type	Petrol	Number of stamps	5	Gearbox	MANUAL
Colour	RED	Last service date	03/09/2021	Gears	5
VIN	SJNTAAE12U1125101	Last service miles	36,728		
Body Style	MPV	MOT Due	31/08/2025		

£65 ADDITIONAL FEE LAST SERVICE 3/9/21 @ 36728 MILES (5 SERVICES) BOOK

### Tyres


NSF	ROTALLA	4.0mm
NSR	ROTALLA	5.0mm
OSF	ROTALLA	4.0mm
OSR	ROTALLA	5.0mm
Spare		

## Features


- Bluetooth connection
- Steering wheel mounted controls
- Air conditioning
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Cruise control
- Radio/CD
- Folding rear seats
- Rear electric windows
- ABS
- Side airbags
- Alloy wheels
- PAS
- Body coloured bumpers
- Front electric windows
- Rear headrests
- Drivers airbag
- Central locking
- Rear wiper
- Electric door mirrors
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Front  
Poor Previous Repair  
Poor Colour





3: Wheel nsf  
Scratched  
Up To 50mm



4: Wing nsf  
Scratched  
Over 25mm Thru Paint



5: A Post ns  
Chipped  
1 To 5



6: Door nsf  
Scratched  
Over 25mm Thru Paint



7: Door nsr  
Scratched  
Over 25mm Thru Paint



8: Tailgate  
Dented  
With Paint Damage



9: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



10: Door osr  
Scratched  
UpTo 25mm Thru Paint



11: Door osf  
Dented  
With Paint Damage



12: Wing osf  
Scratched  
Over 25mm Thru Paint

## Interior

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK