



# VEHICLE INSPECTION REPORT

**GF61FPA**

## Mercedes-Benz A Class A160 Classic SE 5dr CVT Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	27/10/2011	Body Style	Hatchback	Last service miles	92,516
Year	2011	Keys	2	MOT Due	28/09/2025
Mileage	93,561 Miles Warranted	Service history	Yes	CAP Clean	£1,825.00
Fuel Type	Petrol	Service documents	Printout	CAP Average	£1,400.00
Colour	SILVER	Number of stamps	9	CAP Below	£950.00
VIN	WDD1690312J999656	Last service date	17/09/2024	Doors	5

£65 ADDITIONAL FEE LAST SERVICE 17/9/24 @ 92516 MILES ( 9 SERVICE 4 MAIN DEALER) PRINT Poor brakes

### Tyres


NSF	BUDGET	Worn
NSR	LAUFENN	5.0mm
OSF	BUDGET	5.0mm
OSR	GOODYEAR	3.0mm
Spare		

## Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front electric windows
- Metallic Paint
- ESP
- Remote central locking
- Cruise control
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- PAS
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- ABS
- Side airbags
- Steel wheels
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- Drivers airbag
- Central locking

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Front  
Poor Previous Repair  
Poor Paint





3: Wing nsf  
Chipped  
1 To 5



4: Door osf  
Poor Previous Repair  
Rippled UpTo 30%




5: Door nsr  
Poor Previous Repair  
Rippled UpTo 30%



6: Qtr Panel nsr  
Dented  
Over 30mm



7: Bumper Rear  
Scratched  
Over 100mm Thru Paint



8: Bumper Front  
Insecure  
Action Required

No Image



9: Bumper Rear  
Insecure  
Action Required

10: Qtr Panel osr  
Poor Previous Repair  
Rippled UpTo 30%



11: Door osr  
Poor Previous Repair  
Poor Paint



12: Door osf  
Dented  
With Paint Damage



13: Wing osf  
Poor Previous Repair  
Poor Paint

No Image

14: Tyre nsf  
Worn  
Replace

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	Fault	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK