



# VEHICLE INSPECTION REPORT

**HT14CYV**

## Vauxhall Mokka 1.6i SE 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**3**

### Details

Reg. date	19/08/2014	Keys	2	CAP Clean	£1,800.00
Year	2014	Service history	Yes	CAP Average	£1,400.00
Mileage	114,273 Miles Warranted	Service documents	Service Book	CAP Below	£1,000.00
Fuel Type	Petrol	Number of stamps	7	Gearbox	MANUAL
Colour	Blue	Last service date	11/10/2023	Doors	5
VIN	W0LJD7EE3EB760505	Last service miles	88,403		
Body Style	Hatchback	MOT Due	15/11/2025		

£65 ADDITIONAL FEE Last service 11/10/2023 @ 88403 miles (7 SERVICES (5 MAIN DEALER))

### Tyres

NSF	RAPID	6.0mm
NSR	RAPID	6.0mm
OSF	RAPID	6.0mm
OSR	RAPID	6.0mm
Spare		

## Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- ABS
- Traction control
- Leather seat trim
- Cruise control
- Rear wiper
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels
- Front parking sensor
- Telephone
- Air conditioning
- Rear headrests
- ESP
- Central locking
- PAS
- Radio/CD
- Climate control
- Metallic Paint
- Passenger airbag
- Remote central locking

## Photos





## Condition Check



## Damage Photos



1: Door Mirror Assy osf  
Scratched (Painted)  
UpTo 25mm Thru Paint



2: Door osf  
Chipped  
Edge Chip





3: Door osr  
Chipped  
Edge Chip



4: Door nsr  
Chipped  
Edge Chip



5: Door nsf  
Scratched  
UpTo 25mm Thru Paint



6: Wing nsf  
Poor Previous Repair  
Poor Paint



7: Bumper Front  
Poor Previous Repair  
Paint Flake



8: Bonnet  
Poor Previous Repair  
Poor Paint



9: A Post ns  
Poor Previous Repair  
Paint Flake



10: Wheel osr  
Scratched  
Over 50mm



11: Wheel nsr  
Scratched  
Over 50mm



12: Wheel nsf  
Scratched  
Over 50mm

### Interior

**Carpet Condition**                      Average  
**Seat Condition**                      Average

**Upholstery Condition**                      Average  
**Odour**                      No

### Vehicle Inspection Report

**Disclaimer**  
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.  
Additional fees may apply to some vendors.  
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK