

VEHICLE INSPECTION REPORT

LX18KOU

Ford Transit Courier 1.0 EcoBoost Trend Van

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 TBC

nama
GRADE
3

Details

Reg. date 07/03/2018

Year 2018

Mileage 90,920 Miles
Warranted

Fuel Type Petrol

Colour WHITE

VIN WF0WXXTACWHE65088

Body Style Panel Van

Keys 2

MOT Due 14/05/2026

CAP Clean £3,000.00

CAP Average £2,600.00

CAP Below £2,025.00

Gearbox MANUAL

Gears 5

Side door doesn't open

Tyres

NSF BUDGET 4.0mm

NSR BUDGET 4.0mm

OSF BUDGET 4.0mm



OSR BUDGET 4.0mm



Spare

Features


- Bluetooth connection
- Front electric windows
- Rear parking sensor
- Drivers airbag
- Radio/CD
- Central locking
- Air conditioning
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Boot Lid
Dented
Over 30mm



2: Qtr Panel or
Chipped
1 To 5




3: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



4: C Post os
Dented
Over 30mm



5: Door osf
Dented
Over 2 UpTo 10mm



6: Door osf
Scratched
Over 25mm Not Thru Paint



7: Wing osf
Chipped
1 To 5



8: Bumper Front
Chipped
Multiple Chips

No Image



10: Bonnet
Chipped
1 To 5




11: Wing nsf
Dented
With Paint Damage



12: Door nsf
Rusted
Over 5mm



13: Door nsr
Dented
With Paint Damage



14: Roof
Dented
Between 10mm + 30mm



15: Qtr Panel nsr
Dented
Over 30mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK