



# VEHICLE INSPECTION REPORT

GF200DB

## Ford Transit Custom 2.0 EcoBlue 130ps Low Roof Limited Van

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	TBC

nama  
GRADE  
3

### Details

Reg. date	30/06/2020	VIN	WF0YXXTTGYLA34220	Gearbox	MANUAL
Year	2020	Body Style	Panel Van	Gears	6
Mileage	102,526 Miles Warranted	CAP Clean	£7,200.00	Doors	5
Fuel Type	Diesel	CAP Average	£6,450.00		
Colour	WHITE	CAP Below	£5,275.00		

Eml on

### Tyres



NSF	ROADSTONE	3.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	6.0mm
OSR	BUDGET	6.0mm
Spare		

## Features


- Bluetooth connection
- Digital radio
- Passenger airbag
- Cruise control
- Air conditioning
- Central locking
- Park assist camera
- Front electric windows
- Cloth seat trim
- Auxiliary input socket
- Drivers airbag

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Poor Previous Repair  
Poor Paint



2: Bumper Front  
Chipped  
Multiple Chips



No Image



3: Bumper Front  
Scratched  
Over 25mm Not Thru Paint

4: Door Mirror Assy nsf  
Scratched (Painted)  
Over 25mm Thru Paint



5: Wing nsf  
Chipped  
1 To 5

6: Wheel nsf  
Scratched  
Over 50mm



7: Door nsf  
Dented  
With Paint Damage




8: Door nsr  
Dented  
With Paint Damage



9: Wheel nsr  
Scratched  
Over 50mm




10: Qtr Panel nsr  
Chipped  
1 To 5



11: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint



12: Boot Lid  
Chipped  
1 To 5



13: Boot Lid  
Scratched  
Over 25mm Not Thru Paint



14: Qtr Panel osr  
Dented  
Over 30mm



15: Wheel osr  
Scratched  
Over 50mm



16: Door osf  
Scratched  
Over 25mm Thru Paint



17: Wheel osf  
Scratched  
Over 50mm



18: Wing osf  
Chipped  
1 To 5



19: Screen Front  
Chipped  
UpTo 10mm



20: Other  
N/A  
N/A





21: Other  
N/A  
N/A

22: Other  
N/A  
N/A

## Interior

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK