



VEHICLE INSPECTION REPORT

AE20FFV

BMW 4 Series 420i M Sport 5dr Auto [Professional Media]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	09/06/2020	Keys	2	CAP Clean	£14,750.00
Year	2020	Service history	Yes	CAP Average	£13,600.00
Mileage	52,918 Miles Warranted	Service documents	Electronic / Online	CAP Below	£12,500.00
Fuel Type	Petrol	Number of stamps	1	Gearbox	AUTOMATIC
Colour	GREY	Last service date	29/07/2024	Gears	8
VIN	WBA4H32080CE46632	Last service miles	34,256		
Body Style	Coupe	MOT Due	Expired		

£100 ADDITIONAL FEE. EXPIRED MOT.

Services stored in on-board system. Last service 29/07/2024 at 34256 miles (1 main dealer).

Tyres

NSF	BRIDGESTONE	5.0mm
NSR	BRIDGESTONE	4.0mm
OSF	BRIDGESTONE	5.0mm
OSR	BRIDGESTONE	4.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Digital radio
- Air conditioning
- Front head restraints
- Metallic Paint
- ESP
- Central locking
- Cruise control
- PAS
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Front parking sensor
- Rear parking sensor
- Electric door mirrors
- Front armrest
- Rear electric windows
- ABS
- Passenger airbag
- Leather seat trim
- Heated front seat
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- Drivers airbag
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Bumper Front
Chipped
Multiple Chips



3: Wheel osf
Scratched
Over 50mm



4: Door osf
Scratched
Over 25mm Thru Paint



5: Door nsr
Dented
Over 30mm



6: Wheel nsr
Scratched
Over 50mm



7: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



8: Bumper Rear
Scratched
25 to 100mm Thru Paint



9: Wheel osr
Scratched
Up To 50mm



10: Door osr
Dented
Over 30mm



11: Door osf
Dented
With Paint Damage



12: Wing osf
Scratched
Over 25mm Thru Paint



13: Wheel osf
Scratched
Over 50mm



14: B Post ns
Scratched
UpTo 25mm Thru Paint



15: Roof
Chipped
Edge Chip

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
 Additional fees may apply to some vendors.
 Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Turbo Boosting	OK	No Excessive Smoking	OK
Parking Brake	OK		
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK