



VEHICLE INSPECTION REPORT

WG61VXP

Mercedes-Benz A Class A160 BlueEFFICIENCY Classic SE 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	10/02/2012	Body Style	Hatchback	Last service miles	88,416
Year	2012	Keys	2	MOT Due	12/01/2026
Mileage	100,765 Miles Warranted	Service history	Yes	CAP Clean	£1,025.00
Fuel Type	Petrol	Service documents	Printout	CAP Average	£630.00
Colour	SILVER	Number of stamps	7	CAP Below	£275.00
VIN	WDD1690312K030852	Last service date	03/05/2024	Doors	5

LAST SERVICE 3/5/24 @ 88,416 MILES (7 SERVICES 4 MAIN DEALER) PRINT

Tyres


NSF	AVON	4.0mm
NSR	PIRELLI	4.0mm
OSF	AVON	5.0mm
OSR	CONTINENTAL	5.0mm
Spare		

Features


- Bluetooth connection
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- ABS
- Central locking
- PAS
- Radio/CD
- Climate control
- Rear headrests
- Drivers airbag
- Remote central locking
- Rear wiper
- Body coloured bumpers
- Front electric windows
- Metallic Paint
- Isofix child seat anchor points
- Cloth seat trim
- Steering wheel mounted controls
- Electric door mirrors
- Front head restraints
- 3x3 point rear seat belts
- Passenger airbag
- Alloy wheels

Photos






Condition Check



Damage Photos



1: Bumper Rear
Scratched
Over 100mm Thru Paint



2: Boot Lid
Scratched
Over 25mm Not Thru Paint



3: Qtr Panel nsr
Dented
Over 2 UpTo 10mm



4: Door osr
Chipped
1 To 5



5: Door nsf
Dented
With Paint Damage



6: Bonnet
Chipped
Multiple Chips



7: Bumper Front
Scratched
25 to 100mm Thru Paint



8: Bumper Front
Scratched
Over 25mm Not Thru Paint

No Image



9: Wing osf
Scratched
Over 25mm Not Thru Paint

10: Door osf
Scratched
Over 25mm Thru Paint



11: Door osr
Scratched
Over 25mm Thru Paint



12: Qtr Panel osr
Poor Previous Repair
Poor Paint

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK