



VEHICLE INSPECTION REPORT

LA11SNY

Renault Megane 1.6 16V 110 Dynamique TomTom 2dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	23/07/2011	Body Style	Convertible	MOT Due	11/10/2025
Year	2011	Keys	2	CAP Clean	£870.00
Mileage	117,194 Miles Warranted	Service history	Yes	CAP Average	£470.00
Fuel Type	Petrol	Service documents	Printout	CAP Below	£200.00
Colour	Black	Last service date	30/01/2025	Gearbox	MANUAL
VIN	VF1EZ1U0645736287	Last service miles	114,710		

Last service 30/01/2025 @ 114710 miles (3 SERVICES) Fan is always on and seats are stained



Tyres


NSF	BUDGET	4.8mm
NSR	BUDGET	6.8mm
OSF	BUDGET	4.2mm
OSR	BUDGET	4.9mm
Spare	BUDGET	OK

Features


- Navigation system
- Body coloured bumpers
- Air conditioning
- Metallic Paint
- Passenger airbag
- Cloth seat trim
- PAS
- Electric door mirrors
- Front armrest
- ABS
- Alarm
- Leather seat trim
- Telephone
- Electric sunroof
- Front electric windows
- Drivers airbag
- Central locking
- Alloy wheels
- Radio/CD
- Full size spare wheel
- Rear headrests
- ESP
- Remote central locking
- Spare wheel

Photos






Condition Check



Damage Photos



1: Seat Base Cover osf
Torn
UpTo 3mm



2: Wing osf
Chipped
1 To 5

No Image

3: Door osf
Scratched
Over 25mm Not Thru Paint



4: Qtr Panel osr
Chipped
1 To 5

No Image

5: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



6: Bumper Rear
Scratched
25 to 100mm Thru Paint



7: Qtr Panel nsr
Dented
With Paint Damage

No Image

8: Door nsf
Scratched
Over 25mm Not Thru Paint



9: Wing nsf
Chipped
1 To 5



10: Bumper Front
Scratched
25 to 100mm Thru Paint



11: Bonnet
Poor Previous Repair
Poor Paint



12: Screen Front
Chipped
UpTo 10mm



13: Roof
Poor Previous Repair
Paint Flake



14: Carpets Front
Holed
UpTo 3mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		