



# VEHICLE INSPECTION REPORT

**LA54BXH**

## Jeep Grd Cherokee Platnm Crd A - 2685cc

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	31/01/2005	VIN	1J8G8E8A34Y154056	Number of stamps	5
Year	2005	Body Style	Estate	Last service date	18/06/2024
Mileage	142,193 Miles Warranted	Keys	2	Last service miles	134,340
Fuel Type	Diesel	Service history	Yes	MOT Due	30/10/2025
Colour	Black	Service documents	Service Book	Gearbox	AUTOMATIC

Last service 18/06/2024 @ 134340 miles (9 SERVICES (5 MAIN DEALER)) Knocking from front suspension and exhaust smell in cabin.  
Drivers seat adjuster broken

### Tyres

NSF	JOYROAD	4.0mm
NSR	RAPID	7.0mm
OSF	JOYROAD	5.0mm
OSR	JOYROAD	3.0mm
Spare		

## Features


- Cruise control
- Steering wheel mounted controls
- Body coloured bumpers
- Roof rails
- Front armrest
- Rear armrest
- Drivers airbag
- Remote central locking
- Heated front seat
- Trip computer
- Electric door mirrors
- Air conditioning
- Front electric windows
- Rear electric windows
- Rear airbags
- Leather seat trim
- PAS
- Auxiliary input socket
- Electric sunroof
- Climate control
- Front head restraints
- Metallic Paint
- Side airbags
- Alloy wheels
- Rear parking sensor
- Radio/CD
- Front fog lights
- Electrically adjustable drivers seat
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Central locking

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Front  
Cracked  
Over 25mm





3: Wing osf  
Chipped  
Multiple Chips



4: Sill os  
Rusted  
Over 5mm



5: Door osf  
Chipped  
Multiple Chips



6: Wheel osf  
Scratched  
Over 50mm



7: Door osr  
Chipped  
1 To 5



8: Qtr Panel osr  
Chipped  
Multiple Chips



9: Bumper Rear  
Poor Previous Repair  
Paint Flake




10: Boot Lid  
Chipped  
1 To 5



11: Qtr Panel nsr  
Dented  
Over 30mm



12: Door nsf  
Dented  
Over 2 UpTo 10mm



13: Door nsr  
Scratched  
Over 25mm Not Thru Paint



14: Sill ns  
Rusted  
Over 5mm





15: Door nsr  
Scratched  
UpTo 25mm Thru Paint



16: Wing nsf  
Chipped  
1 To 5



17: Screen Front  
Chipped  
UpTo 10mm



18: Wheel nsf  
Scratched  
Over 50mm



19: Wheel nsr  
Scratched  
Over 50mm



20: Wheel osr  
Scratched  
Over 50mm

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		