



# VEHICLE INSPECTION REPORT

**GH17CFY**

## Citroen C1 1.2 PureTech Feel 3dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	27/08/2017	Keys	2	CAP Clean	£2,225.00
Year	2017	Service history	Yes	CAP Average	£1,775.00
Mileage	65,663 Miles Warranted	Service documents	Service Book	CAP Below	£1,325.00
Fuel Type	Petrol	Number of stamps	7	Gearbox	MANUAL
Colour	BLUE	Last service date	08/07/2025	Gears	5
VIN	VF7PAHMTTCGR792576	Last service miles	64,870	Doors	3
Body Style	Hatchback	MOT Due	11/07/2026		

£100 ADDITIONAL FEE.

Last service 08/07/2025 at 64,870- 7 services (4 main dealer)

### Tyres


NSF	AVON	4.0mm
NSR	AVON	4.0mm
OSF	AVON	4.0mm
OSR	AVON	4.0mm
Spare		

## Features


- Bluetooth connection
- Steering wheel mounted controls
- Air conditioning
- Rear headrests
- Isofix child seat anchor points
- Cloth seat trim
- Cruise control
- Audio remote control
- Climate control
- Metallic Paint
- Passenger airbag
- Steel wheels
- PAS
- Digital radio
- Front electric windows
- ABS
- Central locking
- Rear wiper
- Body coloured bumpers
- Height adjustable drivers seat
- Drivers airbag
- Remote central locking

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Poor Previous Repair  
Paint Flake






3: Wing nsf  
Chipped  
1 To 5




4: Door nsf  
Dented  
2 Or Less UpTo 10mm



5: Door nsf  
Scratched  
Over 25mm Not Thru Paint



6: Qtr Panel nsr  
Dented  
Between 10mm + 30mm



7: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint




8: Bumper Rear  
Poor Previous Repair  
Poor Paint



9: Qtr Panel osr  
Dented  
With Paint Damage



10: Door osf  
Dented  
Over 2 UpTo 10mm



11: Door osf  
Scratched  
Over 25mm Not Thru Paint

**Interior**

<b>Carpet Condition</b>	Average	<b>Upholstery Condition</b>	Average
<b>Seat Condition</b>	Average	<b>Odour</b>	No

**Vehicle Inspection Report**

**Disclaimer**  
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.  
Additional fees may apply to some vendors.  
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK