



VEHICLE INSPECTION REPORT

RE69AOL

Fiat 500 1.2 Lounge 3dr Dualogic

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	31/12/2019	Keys	2	CAP Clean	£9,300.00
Year	2019	Service history	Yes	CAP Average	£8,275.00
Mileage	10,374 Miles Warranted	Service documents	Service Book	CAP Below	£7,250.00
Fuel Type	Petrol	Number of stamps	4	Gearbox	AUTOMATIC
Colour	Grey	Last service date	27/02/2025	Doors	3
VIN	ZFA312000JD08785	Last service miles	9,160		
Body Style	Hatchback	MOT Due	27/10/2025		

Last Service - 25.02.2025 at 9160 miles (4 services)

Tyres

NSF	CONTINENTAL	4.0mm
NSR	CONTINENTAL	5.0mm
OSF	AUTOGREEN	5.0mm
OSR	CONTINENTAL	OK
Spare		

Features


- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Front electric windows
- Steering wheel rake adjustment
- Passenger airbag
- Cloth seat trim
- Cruise control
- Steering wheel mounted controls
- Electric door mirrors
- Front head restraints
- ABS
- Side airbags
- Alloy wheels
- PAS
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Rear parking sensor
- Trip computer
- Climate control
- Rear headrests
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
1 To 5



3: Wheel osf
Scratched
Up To 50mm



4: Door osf
Chipped
1 To 5




5: Qtr Panel osr
Chipped
1 To 5



6: Wheel osr
Scratched
Up To 50mm



7: Bumper Rear
Chipped
1 To 5



8: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint

No Image



9: Door nsf
Scratched
UpTo 25mm Not Thru Paint

10: Wheel nsf
Scratched
Over 50mm

Interior

Carpet Condition OK
Seat Condition OK

Upholstery Condition OK
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK