

VEHICLE INSPECTION REPORT

LG18VVY

Volkswagen Polo 1.0 TSI 95 SE 5dr DSG

Inspection		Vehicle	Vehicle		nama
Serious Damage?	No	VAT	Margin		3 Graph
		V5	TBC		
Details					
Reg. date	21/04/2018	VIN	WVWZZZAWZJU024446	CAP Average	£10,400.00
Year	2018	Body Style	Hatchback	CAP Below	£9,325.00
Mileage	14,362 Miles Warranted	Keys	2	Gearbox	SEMI AUTO
		MOT Due	20/04/2026	Gears	7
Fuel Type	Petrol	CAP Clean	£11,450.00	Doors	5
Colour	BLACK		· · · ·		

£100 ADDITIONAL FEE.

Гу	r	е	S

NSF	GOODYEAR	6.0mm	
NSR	GOODYEAR	6.0mm	
OSF	GOODYEAR	6.0mm	
OSR	GOODYEAR	6.0mm	
Snare			

Features

- Bluetooth connection
- Rear parking sensor
 Body coloured bumpers
 Folding rear seats
 Rear electric windows

- ABS
- Passenger airbagCloth seat trim
- Cruise control
- Rear wiper
- Electric door mirrors
 Front electric windows
- Rear headrests
- Drivers airbag Side airbags Alloy wheels

- Front parking sensor
 Steering wheel mounted controls
 Front fog lights
 Front head restraints
 Metallic Paint
 ESP
 PAS
 Digital radio
 Air conditioning
 Height adjustable drivers seat
 3x3 point rear seat belts
 Isofix child seat anchor points

- · Central locking

- Remote central locking

Photos













Eastbourne Car Auctions










Condition Check



Damage Photos



1: Bonnet Chipped 1 To 5



2: Bumper Front Scratched Over 100mm Thru Paint

3: Wheel nsf Scratched Over 50mm

No Image

4: Bumper Front Insecure Action Required



5: Door nsr Chipped Edge Chip



6: Qtr Panel nsr Scratched UpTo 25mm Thru Paint



7: Bumper Rear Scratched Over 100mm Thru Paint



8: Wheel osr Scratched Up To 50mm



9: Qtr Panel osr Scratched Over 25mm Thru Paint



10: Wheel osf Scratched Over 50mm



11: Door osf Scratched UpTo 25mm Thru Paint



12: Roof Scratched Over 25mm Thru Paint

Interior

Carpet ConditionAverageUpholstery ConditionAverageSeat ConditionAverageOdourNo

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs OK	Gearbox 1st and Reverse Test	OK
Brakes OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK