



# VEHICLE INSPECTION REPORT

**GV17ZWE**

## Nissan Qashqai 1.2 DiG-T Tekna [Non-Panoramic] 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**4**

### Details

Reg. date	28/07/2017	Keys	2	CAP Clean	£5,350.00
Year	2017	Service history	Yes	CAP Average	£4,625.00
Mileage	67,086 Miles Warranted	Service documents	Service Book	CAP Below	£3,925.00
Fuel Type	Petrol	Number of stamps	8	Gearbox	MANUAL
Colour	RED	Last service date	07/07/2025	Gears	6
VIN	SJNFEAJ11UZ085447	Last service miles	66,772	Doors	5
Body Style	Hatchback	MOT Due	21/07/2026		

Timing chain kit replaced 05/08/2024 at 59330 miles.  
Last service 07/07/2025 at 66772 miles (8 main dealer services).

### Tyres

NSF	SUNNY	6.0mm
NSR	ACCELERA	6.0mm
OSF	SUNNY	6.0mm
OSR	ACCELERA	6.0mm
Spare		


## Features

- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Electrically adjustable drivers seat
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Fixed panoramic glass roof
- Folding rear seats
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim
- Front parking sensor
- PAS
- Digital radio
- Front fog lights
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Alloy wheels
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front electric windows
- Rear headrests
- Drivers airbag
- Central locking

## Photos











## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Front  
Scratched  
Over 100mm Thru Paint






3: Wing nsf  
Scratched  
Over 25mm Thru Paint




4: Door nsf  
Scratched  
Over 25mm Thru Paint



5: Door nsr  
Scratched  
UpTo 25mm Thru Paint



6: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint



7: Bumper Rear  
Scratched  
Up To 25mm Thru Paint



8: Door osr  
Dented  
Between 10mm + 30mm





9: Door osf  
Dented  
Over 30mm

10: Screen Front  
Chipped  
UpTo 10mm

## Interior

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK