



VEHICLE INSPECTION REPORT

GM65FWY

Peugeot 308 1.6 BlueHDi 100 Active 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC



Details

Reg. date	11/12/2015	VIN	VF3LBBHYBFS204194	CAP Average	£1,600.00
Year	2015	Body Style	Hatchback	CAP Below	£1,200.00
Mileage	102,292 Miles Warranted	Keys	2	Gearbox	MANUAL
Fuel Type	Diesel	MOT Due	06/11/2025	Gears	5
Colour	SILVER	CAP Clean	£2,025.00	Doors	5

£100 ADDITIONAL FEE.

Tyres

NSF	RAPID	6.0mm
NSR	GOODYEAR	5.0mm
OSF	RAPID	6.0mm
OSR	GOODYEAR	5.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Cruise control
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Alloy wheels
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- Drivers airbag
- Central locking
- PAS
- Digital radio
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Chipped
1 To 5



5: Door nsf
Dented
Over 30mm



6: Door nsr
Dented
With Paint Damage



7: Qtr Panel nsr
Dented
With Paint Damage



8: Wheel nsr
Scratched
Over 50mm



9: Bumper Rear
Scratched
Over 100mm Thru Paint



10: Qtr Panel osr
Poor Previous Repair
Rippled UpTo 30%



11: Door osr
Dented
Between 10mm + 30mm



12: Door osf
Chipped
Edge Chip



13: Wheel osf
Scratched
Over 50mm



14: Wing osf
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK