



# VEHICLE INSPECTION REPORT

**GY65SKX**

## Vauxhall Antara 2.2 CDTi Exclusiv 5dr [2WD] [Start Stop]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC



### Details

Reg. date	30/10/2015	VIN	W0LLV6EH3FB061760	CAP Average	£1,175.00
Year	2015	Body Style	Hatchback	CAP Below	£775.00
Mileage	40,228 Miles Warranted	Keys	2	Gearbox	MANUAL
Fuel Type	Diesel	MOT Due	26/09/2025	Gears	6
Colour	WHITE	CAP Clean	£1,600.00	Doors	5

£100 ADDITIONAL FEE. Eml light is on

### Tyres

NSF	ACCELERA	5.0mm
NSR	HANKOOK	5.0mm
OSF	ACCELERA	5.0mm
OSR	HANKOOK	5.0mm
Spare		

## Features


- Heated front seat
- Radio/CD
- Air conditioning
- Front head restraints
- Metallic Paint
- Drivers airbag
- Side airbags
- Alloy wheels
- PAS
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Central locking
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- ABS
- Passenger airbag
- Remote central locking
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- Curtain airbags
- Rear airbags
- Partial leather seat trim

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Dented  
Between 10mm + 30mm



2: Door Mirror Assy osf  
Scratched (Painted)  
UpTo 25mm Thru Paint





3: Door osf  
Chipped  
Edge Chip



4: Door osr  
Scratched  
Over 25mm Thru Paint



5: Qtr Panel osr  
Scratched  
UpTo 25mm Thru Paint



6: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



7: Door nsr  
Scratched  
UpTo 25mm Thru Paint



8: Door nsf  
Dented  
Between 10mm + 30mm

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK