



VEHICLE INSPECTION REPORT

LS61WYM

Fiat 500 0.9 TwinAir Lounge 3dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	29/12/2011	Keys	1	CAP Clean	£1,550.00
Year	2011	Service history	Yes	CAP Average	£1,125.00
Mileage	58,931 Miles Warranted	Service documents	Printout	CAP Below	£725.00
Fuel Type	Petrol	Number of stamps	1	Gearbox	MANUAL
Colour	GREY	Last service date	05/01/2024	Gears	5
VIN	ZFA31200000728506	Last service miles	52,873	Doors	3
Body Style	Hatchback	MOT Due	20/02/2026		

£100 ADDITIONAL FEE. LAST SERVICE 5/1/24 @ 52,873 MILES (1 SERVICE) PRINT Noisy steering, engine ticking

Tyres

NSF

NSR

OSF

OSR


Spare

Photos





Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Scratched
Over 25mm Thru Paint



5: Door nsf
Dented
Over 30mm



6: Wheel nsr
Scratched
Over 50mm



7: Qtr Panel nsr
Dented
Over 30mm



8: Bumper Rear
Dented
With Paint Damage



9: Bumper Rear Moulding
Broken
Replace



10: Wheel osr
Scratched
Over 50mm



11: Qtr Panel osr
Poor Previous Repair
Poor Paint



12: Door osf
Dented
With Paint Damage



13: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition -
Seat Condition -

Upholstery Condition -
Odour -

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK