

VEHICLE INSPECTION REPORT

YC61JUO

Vauxhall Zafira 1.8i Excite 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC



Details

Reg. date	04/11/2011	VIN	W0L0AHM75B2151919	CAP Average	£610.00
Year	2011	Body Style	MPV	CAP Below	£275.00
Mileage	80,783 Miles Warranted	Keys	1	Gearbox	MANUAL
Fuel Type	Petrol	MOT Due	Expired	Gears	5
Colour	BLACK	CAP Clean	£1,025.00		

Eml light is on , exhaust blowing


Tyres


NSF	UNIROYAL	6.0mm
NSR	UNIROYAL	6.0mm
OSF	UNIROYAL	6.0mm
OSR	HANKOOK	6.0mm
Spare		

Features


- PAS
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- Isofix child seat anchor points
- Remote central locking
- Rear wiper
- Electric door mirrors
- Front electric windows
- Metallic Paint
- Passenger airbag
- Cloth seat trim
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- 3x3 point rear seat belts
- Side airbags
- Alloy wheels
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Bumper Front
Insecure
Action Required



4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Scratched
Over 25mm Thru Paint



6: Door osf
Scratched
Over 25mm Thru Paint



7: Sill ns
Dented
Over 30mm



8: Door nsr
Dented
With Paint Damage



9: Wheel nsr
Scratched
Over 50mm



10: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



11: Bumper Rear
Dented
With Paint Damage



12: Qtr Panel osr
Scratched
Over 25mm Thru Paint



13: Door osr
Scratched
Over 25mm Thru Paint



14: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint



15: Door osf
Scratched
Over 25mm Thru Paint



16: Wheel osf
Scratched
Over 50mm



17: Wing osf
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK