

# VEHICLE INSPECTION REPORT

**KR09XUH**

## Peugeot 308 1.6 VTi S 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC



### Details

Reg. date	30/06/2009	VIN	VF34C5FWF9S100698	CAP Average	£530.00
Year	2009	Body Style	Hatchback	CAP Below	£250.00
Mileage	89,196 Miles Warranted	Keys	1	Gearbox	AUTOMATIC
Fuel Type	Petrol	MOT Due	09/07/2026	Gears	4
Colour	BLACK	CAP Clean	£920.00	Doors	5

### Tyres


NSF	DAVANTI	4.0mm
NSR	BUDGET	5.0mm
OSF	DAVANTI	4.0mm
OSR	BUDGET	5.0mm

### Spare

## Features


- PAS
- Electric door mirrors
- Front electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Rear wiper
- Front fog lights
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Digital radio
- Air conditioning
- Rear electric windows
- Curtain airbags
- Side airbags
- Steel wheels
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- Drivers airbag
- Central locking

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Front  
Scratched  
25 to 100mm Thru Paint





3: Wing nsf  
Scratched  
UpTo 25mm Thru Paint



4: Door Mirror Assy nsf  
Scratched (Painted)  
Over 25mm Thru Paint



5: Door nsf  
Dented  
Between 10mm + 30mm



6: Door nsr  
Dented  
Between 10mm + 30mm



7: Qtr Panel osr  
Dented  
Over 30mm



8: Bumper Rear  
Scratched  
Over 100mm Thru Paint





9: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



10: Door osr  
Dented  
With Paint Damage



11: Door osf  
Dented  
Between 10mm + 30mm



12: Wing osf  
Scratched  
Over 25mm Thru Paint



13: Roof  
Scratched  
Over 25mm Thru Paint



14: Aerial  
Missing  
Replace



15: Roof Lining  
Scuffed  
Over 25mm

## Interior

Carpet Condition  
Seat Condition

Average  
Average

Upholstery Condition  
Odour

Average  
No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK