



VEHICLE INSPECTION REPORT

GK70KUH

Nissan Juke 1.0 DiG-T 114 N-Connecta 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC



Details

Reg. date	04/01/2021	VIN	SJNFAAF16U1088690	CAP Average	£9,950.00
Year	2021	Body Style	Hatchback	CAP Below	£8,750.00
Mileage	26,413 Miles Warranted	Keys	2	Gearbox	MANUAL
Fuel Type	Petrol	MOT Due	10/10/2025	Gears	6
Colour	SILVER	CAP Clean	£11,100.00	Doors	5

£100 ADDITIONAL FEE Car shakes while idle

Tyres

NSF

NSR

OSF


OSR

Spare

Features


- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- Drivers airbag
- Central locking
- Cruise control
- PAS
- Digital radio
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Navigation system
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Alloy wheels

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Dented
Between 10mm + 30mm



5: Door nsf
Poor Previous Repair
Rippled UpTo 30%



6: Bumper Rear
Poor Previous Repair
Poor Colour



7: B Post os
Dented
Between 10mm + 30mm



8: Door osf
Dented
Over 30mm



9: Wing osf
Dented
Over 30mm



10: Wheel osf
Scratched
Over 50mm



11: Roof
Scratched
Over 25mm Thru Paint



12: Door nsr
Poor Previous Repair
Poor Colour



13: Qtr Panel nsr
Poor Previous Repair
Poor Colour

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK