



VEHICLE INSPECTION REPORT

GY72XPM

MG Mg Hs EXCLUSIVE DCT

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC



Details

Reg. date	31/10/2022	VIN	LSJA24U99NN146629	CAP Average	£9,250.00
Year	2022	Body Style	Estate	CAP Below	£8,100.00
Mileage	91,200 Miles Warranted	Keys	2	Gearbox	SEMI AUTO
Fuel Type	Petrol	MOT Due	30/10/2025	Gears	7
Colour	BLACK	CAP Clean	£10,400.00		

£100 ADDITIONAL FEE

Tyres

NSF	MICHELIN	5.0mm
NSR	MICHELIN	5.0mm
OSF	MICHELIN	5.0mm
OSR	MICHELIN	5.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Electrically adjustable passenger seat
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Cruise control
- PAS
- Digital radio
- Opening panoramic glass roof
- Folding rear seats
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Lane departure warning
- Remote central locking
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front armrest
- Rear electric windows
- ABS
- Passenger airbag
- Leather seat trim
- Navigation system
- Rear wiper
- Electric door mirrors
- Electrically adjustable drivers seat
- Front electric windows
- Rear headrests
- Drivers airbag
- Side airbags
- Alloy wheels

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Chipped
Multiple Chips



3: Wing nsf
Chipped
Multiple Chips



4: Door nsf
Scratched
Over 25mm Thru Paint



5: Door nsr
Scratched
Over 25mm Thru Paint



6: Wheel nsr
Scratched
Over 50mm



7: Qtr Panel nsr
Chipped
1 To 5



8: Door osr
Dented
Between 10mm + 30mm



9: Wing osf
Chipped
1 To 5



10: Wheel osf
Scratched
Up To 50mm



11: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



12: Door osf
Dented
Over 30mm



13: Roof
Chipped
Multiple Chips

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		