



VEHICLE INSPECTION REPORT

KD16UJZ

Volkswagen Polo 1.2 TSI Match 5dr

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 TBC

nama

GRADE

1

Details

Reg. date 29/07/2016

VIN WVWZZZ6RZGU078324

CAP Average £5,475.00

Year 2016

Body Style Hatchback

CAP Below £4,625.00

Mileage 55,388 Miles
Warranted

Keys 2

Gearbox MANUAL

Fuel Type Petrol

MOT Due 05/02/2026

Gears 5

Colour BLACK

CAP Clean £6,300.00

Doors 5

£65 ADDITIONAL FEE

Tyres

NSF

NSR

OSF


OSR

Spare

Features

- Bluetooth connection
- Rear parking sensor
- Digital radio
- Climate control
- Rear electric windows
- ABS
- Central locking
- Cruise control
- Rear wiper
- Body coloured bumpers
- Front electric windows
- Rear headrests
- Drivers airbag
- Remote central locking
- Front parking sensor
- Steering wheel mounted controls
- Electric door mirrors
- Front head restraints
- Metallic Paint
- Passenger airbag
- Cloth seat trim
- PAS
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Traction control
- Alloy wheels

Condition Check



Damage Photos

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		

Windows

OK

Radio

OK

Steering

OK