

VEHICLE INSPECTION REPORT

LS69PTY

Toyota Prius+ 1.8 VVTi Icon TSS 5dr CVT Auto

Inspection

Serious Damage? No

Vehicle

VAT VAT Qualifying

V5 TBC

nama
GRADE
4

Details

Reg. date	10/10/2019	VIN	JTDZS3EU10J046381	CAP Average	£12,750.00
Year	2019	Body Style	MPV	CAP Below	£11,650.00
Mileage	58,106 Miles Warranted	Keys	2	Gearbox	CVT
Fuel Type	Hybrid Electric	MOT Due	28/08/2025	Gears	1
Colour	GREY	CAP Clean	£13,900.00		

Tyres

NSF	BUDGET	4.0mm
NSR	KORMORAN	4.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	4.0mm

Spare

Features


- Bluetooth connection
- PAS
- Digital radio
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Passenger airbag
- Cloth seat trim
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Curtain airbags
- Traction control
- Alloy wheels
- Park assist camera
- Audio remote control
- Air conditioning
- Front head restraints
- Metallic Paint
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Bumper Rear
Scratched
Over 100mm Thru Paint



2: Boot Lid
Scratched
UpTo 25mm Thru Paint



3: Qtr Panel osr
Dented
With Paint Damage



4: Door osr
Chipped
1 To 5



5: Door osr
Scratched
Over 25mm Not Thru Paint



6: Door osf
Chipped
1 To 5



7: Door osf
Scratched
Over 25mm Not Thru Paint



8: Wing osf
Chipped
1 To 5



9: Bumper Front
Scratched
Over 100mm Thru Paint



10: Bonnet
Dented
With Paint Damage



11: Wing nsf
Chipped
1 To 5



12: Door nsf
Chipped
Multiple Chips



13: Door nsr
Dented
With Paint Damage



14: Qtr Panel nsr
Dented
With Paint Damage

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK