



VEHICLE INSPECTION REPORT

LT16FX

Nissan Qashqai 1.5 dCi N-Tec+ 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	01/03/2016	Keys	2	CAP Clean	£3,900.00
Year	2016	Service history	Yes	CAP Average	£3,325.00
Mileage	102,547 Miles Warranted	Service documents	Service Book	CAP Below	£2,775.00
Fuel Type	Diesel	Number of stamps	9	Gearbox	MANUAL
Colour	RED	Last service date	19/02/2025	Gears	6
VIN	SJNFAAJ11U1626990	Last service miles	97,500	Doors	5
Body Style	Hatchback	MOT Due	08/03/2026		

Last service s19/02/2025 at 97,500 miles- 9 services (8 main dealer) Engine tapping

Tyres

NSF	MATADOR	5.0mm
NSR	CONTINENTAL	5.0mm
OSF	CONTINENTAL	5.0mm
OSR	MICHELIN	5.0mm
Spare		


Features

- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Fixed panoramic glass roof
- Front armrest
- Rear electric windows
- ABS
- Passenger airbag
- Cloth seat trim
- Cruise control
- PAS
- Digital radio
- Front fog lights
- Front electric windows
- Rear headrests
- Drivers airbag
- Side airbags
- Alloy wheels
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Metallic Paint
- ESP
- Central locking
- Navigation system
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking

Photos



Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Chipped
Multiple Chips



3: Wing nsf
Scratched
Over 25mm Thru Paint



4: Wheel nsf
Scratched
Over 50mm



5: Door nsf
Dented
With Paint Damage



6: Door nsr
Dented
Over 30mm



7: Wheel nsr
Scratched
Up To 50mm



8: Qtr Panel osr
Dented
Between 10mm + 30mm



9: Wheel osr
Scratched
Over 50mm



10: Door osr
Dented
2 Or Less UpTo 10mm



11: Door osf
Dented
2 Or Less UpTo 10mm



12: Wheel osf
Scratched
Up To 50mm



13: Wing osf
Chipped
1 To 5



14: Switches And Controls
Broken
Replace

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK