

VEHICLE INSPECTION REPORT

NV67CKP

Peugeot Partner 850 1.6 BlueHDi 100 Professional Van [non SS]

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	TBC



Details

Reg. date	13/12/2017	VIN	VF37DBHY6HJ829309	CAP Below	£1,625.00
Year	2017	Body Style	Panel Van	Gearbox	MANUAL
Mileage	113,177 Miles Warranted	MOT Due	12/12/2025	Gears	5
Fuel Type	Diesel	CAP Clean	£2,525.00	Doors	5
Colour	WHITE	CAP Average	£2,150.00		

Key damaged

Tyres


NSF	BUDGET	4.0mm
NSR	BUDGET	4.0mm
OSF	ROTELLA	2.0mm
OSR	TRIANGLE	4.0mm
Spare		

Features


- Bluetooth connection
- Front electric windows
- Cruise control
- Drivers airbag
- Digital radio
- Central locking
- Air conditioning
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Chipped
Multiple Chips



3: Wing nsf
Poor Previous Repair
Poor Paint



4: Door nsf
Dented
Over 30mm



5: Door nsr
Dented
Over 30mm



6: Qtr Panel nsr
Dented
Over 30mm



7: Boot Lid
Dented
With Paint Damage



8: Roof
Dented
Over 30mm




9: Qtr Panel osr
Dented
Over 30mm



10: Door osf
Dented
Over 30mm



11: Wing osf
Dented
Over 30mm



12: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK