



# VEHICLE INSPECTION REPORT

AO22KRV

## Volkswagen Golf 1.5 TSI 150 Style 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	17/05/2022	Keys	2	CAP Clean	£17,800.00
Year	2022	Service history	Yes	CAP Average	£16,600.00
Mileage	17,300 Miles Warranted	Service documents	Printout	CAP Below	£15,450.00
Fuel Type	Petrol	Number of stamps	2	Gearbox	MANUAL
Colour	SILVER	Last service date	20/12/2024	Gears	6
VIN	WVWZZZCDZNW185775	Last service miles	13,225	Doors	5
Body Style	Hatchback	MOT Due	16/05/2026		

Last Service - 20.12.2024 at 13225 miles (2 main dealer services)

### Tyres

NSF	NEXEN	3.0mm
NSR	NEXEN	4.0mm
OSF	NEXEN	4.0mm
OSR	NEXEN	4.0mm
Spare		

## Features


- Bluetooth connection
- Rear parking sensor
- Digital radio
- Climate control
- Height adjustable drivers seat
- Drivers airbag
- Traction control
- Alloy wheels
- Cruise control
- Rear wiper
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Front parking sensor
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- PAS
- Audio remote control
- Air conditioning
- Front head restraints
- ABS
- Side airbags
- Cloth seat trim

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Chipped  
Multiple Chips

No Image



3: Bumper Front  
Scratched  
Over 25mm Not Thru Paint

4: Door nsf  
Chipped  
1 To 5

No Image



5: Door nsr  
Scratched  
Over 25mm Not Thru Paint

6: Bumper Rear  
Chipped  
Multiple Chips

No Image



7: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint

8: Door osf  
Dented  
2 Or Less UpTo 10mm

## Interior



**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK