

VEHICLE INSPECTION REPORT

GX57KPO

Ford Fiesta 16V ZETEC CLIMATE

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	17/06/2008	Colour	GREY	Service history	None
Year	2008	VIN	WF0DXXGAJD7M84123	MOT Due	30/01/2026
Mileage	86,968 Miles Warranted	Body Style	Hatchback	Doors	3
Fuel Type	Petrol	Keys	2		

Clutch Replaced 07.12.2021 No Service History EML Light Is On And Boot Only Opens With Key And Seats Are Stained Both Front Seats Do Not Go Forward

Tyres

NSF	BUDGET	6.7mm
NSR	LAUFENN	4.9mm
OSF	BUDGET	6.7mm
OSR	LAUFENN	4.9mm
Spare	BUDGET	OK

Features


- PAS
- Body coloured bumpers
- Rear headrests
- ESP
- Remote central locking
- Rear wiper
- Electric door mirrors
- Metallic Paint
- Passenger airbag
- Cloth seat trim
- Telephone
- Air conditioning
- ABS
- Alarm
- Alloy wheels
- Radio/CD
- Front electric windows
- Drivers airbag
- Central locking
- Spare wheel

Photos





Condition Check



Damage Photos



1: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Not Thru Paint



2: Door Moulding osf
Scratched (Painted)
UpTo 25mm Thru Paint

No Image



3: Door osf
Scratched
Over 25mm Not Thru Paint

4: Qtr Panel osr
Dented
Between 10mm + 30mm

No Image



5: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint

6: Bumper Rear
Scratched
25 to 100mm Thru Paint



7: Door nsf
Chipped
Edge Chip



8: Door Moulding nsf
Scratched (Painted)
UpTo 25mm Thru Paint



9: Wing nsf
Dented
Between 10mm + 30mm



10: Bumper Front
Scratched
Over 25mm Not Thru Paint



11: Bumper Front
Scratched
UpTo 25mm Thru Paint



12: Bonnet
Chipped
1 To 5



13: Seat Back Cover osf
Missing
Replace

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK