



VEHICLE INSPECTION REPORT

RE66TRV

Renault Kangoo ML19dCi 75 Business+ Van

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	30/09/2016	VIN	VF1FW17BD54440060	Last service date	07/03/2025
Year	2016	Body Style	Panel Van	Last service miles	134,547
Mileage	138,881 Miles Warranted	Service history	Yes	MOT Due	Expired
Fuel Type	Diesel	Service documents	Service Book	Gearbox	MANUAL
Colour	WHITE	Number of stamps	6	Gears	6

Last Service - 07.03.2025 at 134547 miles (6 main dealer services)
Timing Belt replaced 18.055.2022 @ 95156 miles

Tyres

NSF	MICHELIN	2.0mm
NSR	MICHELIN	4.0mm
OSF	MICHELIN	2.0mm
OSR	MICHELIN	4.0mm
Spare		

Features


- Radio/CD
- Air conditioning
- Front electric windows
- Drivers airbag
- Passenger airbag
- Central locking
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Chipped
Multiple Chips



3: Wing nsf
Scratched
Over 25mm Thru Paint



4: Door nsf
Chipped
1 To 5



5: Door nsr
Scratched
Over 25mm Not Thru Paint



6: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



7: Boot Lid
Chipped
Multiple Chips



8: Bumper Rear
Scratched
25 to 100mm Thru Paint



9: Qtr Panel osr
Scratched
Over 25mm Thru Paint

10: Door osf
Dented
With Paint Damage



11: Wing osf
Scratched
Over 25mm Not Thru Paint

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK