



VEHICLE INSPECTION REPORT

MW63HEV

Peugeot 208 1.4 HDi Active 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	N/A

nama
GRADE
3

Details

Reg. date	06/12/2013	VIN	VF3CC8HR0DW073908	CAP Average	£1,600.00
Year	2013	Body Style	Hatchback	CAP Below	£1,175.00
Mileage	60,063 Miles Warranted	Keys	2	Gearbox	MANUAL
Fuel Type	Diesel	MOT Due	05/12/2025	Gears	5
Colour	GREY	CAP Clean	£2,000.00	Doors	5

£100 ADDITIONAL FEE.



Tyres


NSF	INVOVIC	4.0mm
NSR	AUTOGREEN	4.0mm
OSF	INVOVIC	3.0mm
OSR	AUTOGREEN	5.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Digital radio
- Climate control
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Cruise control
- Telephone
- Body coloured bumpers
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Side airbags
- Cloth seat trim
- PAS
- Trip computer
- Electric door mirrors
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Traction control
- Alloy wheels
- Rear wiper
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Poor Previous Repair
Rippled Over 30%



3: Wheel osf
Scratched
Over 50mm



4: Door osf
Chipped
1 To 5



5: Door osr
Chipped
1 To 5



6: Wheel osr
Scratched
Over 50mm



7: Bumper Rear
Scratched
25 to 100mm Thru Paint



8: Wheel nsr
Scratched
Over 50mm



9: Door nsr
Chipped
1 To 5



10: Door nsf
Dented
Between 10mm + 30mm



11: Wing nsf
Chipped
1 To 5



12: Wheel nsf
Scratched
Over 50mm



13: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK