



VEHICLE INSPECTION REPORT

AO22UWK

Toyota Aygo X 1.0 VVT-i Pure 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	30/06/2022	Keys	2	CAP Clean	£8,475.00
Year	2022	Service history	Yes	CAP Average	£7,450.00
Mileage	49,800 Miles Warranted	Service documents	Service Book	CAP Below	£6,425.00
Fuel Type	Petrol	Number of stamps	2	Gearbox	MANUAL
Colour	BLACK	Last service date	07/02/2025	Gears	5
VIN	JTDAGNAC500020637	Last service miles	42,763	Doors	5
Body Style	Hatchback	MOT Due	29/06/2026		

Last Service - 07.02.2025 at 42763 miles (2 main dealer services)

Tyres

NSF	MICHELIN	2.0mm
NSR	GOODYEAR	4.0mm
OSF	MICHELIN	2.0mm
OSR	MICHELIN	3.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Front electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Cruise control
- Steering wheel mounted controls
- Electric door mirrors
- Front head restraints
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Park assist camera
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- ABS
- Side airbags
- Cloth seat trim
- PAS
- Digital radio
- Climate control
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Door nsf
Dented
Over 2 UpTo 10mm



5: Door nsr
Chipped
1 To 5



6: Wheel nsr
Scratched
Up To 50mm



7: Bumper Rear
Scratched
25 to 100mm Thru Paint



8: Bumper Rear
Scratched
Over 25mm Not Thru Paint



9: Door osr
Scratched
Over 25mm Thru Paint



10: Door osf
Scratched
Over 25mm Thru Paint



11: Wing osf
Chipped
1 To 5



12: Wheel osf
Scratched
Up To 50mm



13: Wheel osf
Scratched
Up To 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK