



46 Brampton Road
Eastbourne
BN229BN

01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GJ65OMT

Volkswagen Golf 1.4 TSI 150 GT 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	24/09/2015	Keys	2	CAP Clean	£8,425.00
Year	2015	Service history	Yes	CAP Average	£7,425.00
Mileage	44,878 Miles Warranted	Service documents	Service Book	CAP Below	£6,375.00
Fuel Type	Petrol	Number of stamps	4	Gearbox	MANUAL
Colour	SILVER	Last service date	19/09/2023	Gears	6
VIN	WVWZZZAUZGP035039	Last service miles	4	Doors	5
Body Style	Hatchback	MOT Due	24/10/2025		

Last Service -19.09.2023 at 36815 miles (4 services services)

Tyres

NSF	GOODYEAR	5.0mm
NSR	PIRELLI	6.0mm
OSF	GOODYEAR	5.0mm
OSR	GOODYEAR	6.0mm
Spare	BUDGET	OK

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels
- Cruise control
- Rear wiper
- Electric door mirrors
- Rear electric windows
- ESP
- Central locking
- Front parking sensor
- Telephone
- Air conditioning
- Rear headrests
- Passenger airbag
- Remote central locking
- Navigation system
- Radio/CD
- Front armrest
- ABS
- Traction control
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Wing osf
Chipped
1 To 5



2: Door osf
Chipped
Edge Chip



3: Tailgate
 Scratched
 Over 25mm Not Thru Paint



4: Door nsf
 Scratched
 UpTo 25mm Thru Paint



5: Wing nsf
 Scratched
 Over 25mm Thru Paint



6: Bumper Front
 Scratched
 25 to 100mm Thru Paint



7: Bumper Front
 Chipped
 1 To 5



8: Bonnet
 Chipped
 1 To 5



9: Wheel nsf
Scratched
Up To 50mm



10: Sill ns
Dented
With Paint Damage



11: Door nsr
Scratched
UpTo 25mm Thru Paint

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK