



VEHICLE INSPECTION REPORT

BF64BUJ

Nissan Juke 1.6 Acenta Premium 5dr Xtronic

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	24/09/2014	Keys	2	CAP Clean	£4,350.00
Year	2014	Service history	Yes	CAP Average	£3,750.00
Mileage	69,373 Miles Warranted	Service documents	Service Book	CAP Below	£3,150.00
Fuel Type	Petrol	Number of stamps	11	Gearbox	CVT
Colour	YELLOW	Last service date	16/09/2024	Gears	5
VIN	SJNFBAF15U7033562	Last service miles	64,494	Doors	5
Body Style	Hatchback	MOT Due	23/09/2025		

Last Service - 16.09.2024 at 64494 miles (11 services)

Tyres


NSF	BUDGET	4.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Body coloured bumpers
- Front armrest
- Solid Paint
- Passenger airbag
- Remote central locking
- Cruise control
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Traction control
- Cloth seat trim
- Navigation system
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels
- Park assist camera
- Radio/CD
- Climate control
- Rear headrests
- ESP
- Central locking

Photos






Condition Check




Damage Photos



1: Door osf
Dented
2 Or Less UpTo 10mm




2: Bumper Rear
Poor Previous Repair
Paint Flake



3: Door nsf
Dented
2 Or Less UpTo 10mm



4: Bumper Front
Chipped
1 To 5



5: Bonnet
Chipped
1 To 5



6: Fog Lamp Surround ns
Scratched (Painted)
Over 25mm Thru Paint



7: Wheel nsf
Scratched
Up To 50mm



8: Wheel nsr
Scratched
Up To 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK