



VEHICLE INSPECTION REPORT

BF18KYR

Vauxhall Insignia 1.5T SRi 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
2

Details

Reg. date	22/05/2018	Keys	2	CAP Clean	£5,475.00
Year	2018	Service history	Yes	CAP Average	£4,775.00
Mileage	70,142 Miles Warranted	Service documents	Service Book	CAP Below	£4,075.00
Fuel Type	Petrol	Number of stamps	6	Gearbox	MANUAL
Colour	BLACK	Last service date	03/04/2024	Gears	6
VIN	W0VZS6EB0J1152778	Last service miles	57,422	Doors	5
Body Style	Hatchback	MOT Due	21/05/2025		

Last Service - 03.04.2024 at 57422 miles (6 main dealer services)


Tyres

NSF	UNIROYAL	6.0mm
NSR	UNIROYAL	6.0mm
OSF	UNIROYAL	6.0mm
OSR	UNIROYAL	6.0mm
Spare	BUDGET	OK

Features


- Bluetooth connection
- Park assist camera
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels
- Cruise control
- PAS
- Radio/CD
- Climate control
- Rear headrests
- ESP
- Central locking
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Passenger airbag
- Remote central locking
- Heated front seat
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Traction control
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Wing osf
Scratched
Over 25mm Not Thru Paint



2: Wheel osf
Scratched
Up To 50mm



3: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



4: Bumper Rear
Scratched
25 to 100mm Thru Paint



5: Bumper Rear
Scratched
Over 25mm Not Thru Paint



6: Tailgate
Dented
2 Or Less UpTo 10mm



7: Qtr Panel nsr
Dented
2 Or Less UpTo 10mm



8: Wing nsf
Scratched
Over 25mm Not Thru Paint



9: Bumper Front
Scratched
UpTo 25mm Thru Paint



10: Bonnet
Chipped
1 To 5



11: Wheel osr
Scratched
Up To 50mm



12: Wheel nsr
Scratched
Over 50mm



13: Wheel nsf
Scratched
Up To 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK