



VEHICLE INSPECTION REPORT

WX63DCF

Volkswagen Golf 2.0 TDI GT 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	06/09/2013	Keys	2	CAP Clean	£5,375.00
Year	2013	Service history	Yes	CAP Average	£4,650.00
Mileage	78,436 Miles Warranted	Service documents	Service Book	CAP Below	£3,925.00
Fuel Type	Diesel	Number of stamps	4	Gearbox	MANUAL
Colour	BLACK	Last service date	27/08/2024	Gears	6
VIN	WVWZZZAUZEP023295	Last service miles	76,131	Doors	5
Body Style	Hatchback	MOT Due	05/09/2025		

£65 ADDITIONAL FEE Last service 27/08/2024 @ 76131 miles (4 SERVICES 1 MAIN DEALER)

Tyres

NSF	DUNLOP	5.0mm
NSR	DUNLOP	6.0mm
OSF	DUNLOP	5.0mm
OSR	DUNLOP	6.0mm
Spare	BUDGET	OK

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- ABS
- Traction control
- Cloth seat trim
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels
- Navigation system
- Telephone
- Air conditioning
- Rear headrests
- ESP
- Central locking
- PAS
- Radio/CD
- Front armrest
- Metallic Paint
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Wing osf
Chipped
1 To 5



2: Door osf
Chipped
Edge Chip



3: Bumper Rear
Scratched
25 to 100mm Thru Paint



4: Door nsf
Chipped
Edge Chip



5: Door nsf
Chipped
1 To 5



6: Bumper Front
Scratched
25 to 100mm Thru Paint



7: Bonnet
Chipped
1 To 5



8: Screen Front
Chipped
UpTo 10mm

No Image



10: Wheel osf
Scratched
Over 50mm



11: Wheel nsf
Scratched
Up To 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK