



46 Brampton Road  
Eastbourne  
BN229BN

01323 520295 | no-reply@ebca.co.uk

# VEHICLE INSPECTION REPORT

**GV66CLU**

## Mercedes-Benz C Class C350e Sport Premium 4dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	25/11/2016	Body Style	Saloon	MOT Due	25/07/2025
Year	2016	Keys	2	CAP Clean	£11,600.00
Mileage	24,363 Miles Warranted	Service history	Yes	CAP Average	£10,500.00
Fuel Type	Hybrid Electric	Service documents	Printout	CAP Below	£9,400.00
Colour	SILVER	Last service date	11/07/2024	Gearbox	Automatic
VIN	WDD2050472F418123	Last service miles	22,417	Doors	4

£65 ADDITIONAL FEE Last service 11/07/2024 @ 22417 miles (8 MAIN DEALER SERVICES)

### Tyres



NSF	HANKOOK	5.0mm
NSR	APOLLO	6.0mm
OSF	HANKOOK	5.0mm
OSR	TOYO	5.0mm
Spare		

## Features


- Bluetooth connection
- Navigation system
- Telephone
- Electric sunroof
- Electrically adjustable passenger seat
- Rear headrests
- ESP
- Central locking
- Cruise control
- Park assist camera
- Radio/CD
- Air conditioning
- Front armrest
- Metallic Paint
- Passenger airbag
- Remote central locking
- Front parking sensor
- PAS
- Body coloured bumpers
- Climate control
- Front electric windows
- ABS
- Traction control
- Leather seat trim
- Heated front seat
- Rear parking sensor
- Electric door mirrors
- Electrically adjustable drivers seat
- Rear electric windows
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels

## Photos





## Condition Check



## Damage Photos



1: Door osf  
Chipped  
Edge Chip



2: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint





3: Wheel nsf  
 Scratched  
 Up To 50mm



4: Wing nsf  
 Scratched  
 Over 25mm Not Thru Paint



5: Bumper Front  
 Scratched  
 25 to 100mm Thru Paint

**Interior**

**Carpet Condition**                      Average  
**Seat Condition**                      Average

**Upholstery Condition**              Average  
**Odour**                                      No

**Vehicle Inspection Report**

**Disclaimer**  
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.  
 Additional fees may apply to some vendors.  
 Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		