



46 Brampton Road
Eastbourne
BN229BN

01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GY65BZR

Vauxhall Corsa 1.4 Limited Edition 3dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	20/10/2015	Service history	Yes	CAP Average	£3,050.00
Year	2015	Service documents	Service Book	CAP Below	£2,450.00
Mileage	61,660 Miles Warranted	Number of stamps	7	Gearbox	MANUAL
Fuel Type	Petrol	Last service date	10/10/2023	Gears	5
Colour	GREY	Last service miles	52,087	Doors	3
VIN	W0L0XEP08F4065850	MOT Due	19/10/2025		
Body Style	Hatchback	CAP Clean	£3,625.00		

£100 ADDITIONAL FEE Last service 10/10/2023 @ 52087 miles (7 SERVICES (5 MAIN DEALER)) Rattle from engine

Tyres

NSF	BUDGET	4.0mm
NSR	BUDGET	4.0mm
OSF	BUDGET	5.0mm
OSR	HAIDA	4.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Body coloured bumpers
- Climate control
- Rear headrests
- Curtain airbags
- Traction control
- Alloy wheels
- Cruise control
- Trip computer
- Electric door mirrors
- Front electric windows
- Metallic Paint
- Drivers airbag
- Central locking
- PAS
- Audio remote control
- Front fog lights
- Front head restraints
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Rear wiper
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- ABS
- Passenger airbag
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wing osf
Chipped
1 To 5



4: Wheel osf
Scratched
Over 50mm



5: Door osf
Chipped
1 To 5



6: Qtr Panel osr
Dented
With Paint Damage



7: Wheel osr
Scratched
Over 50mm



8: Bumper Rear
Scratched
25 to 100mm Thru Paint



9: Boot Lid
Chipped
1 To 5



10: Qtr Panel nsr
Dented
Over 30mm



11: Wheel nsr
Scratched
Over 50mm



12: Door nsf
Chipped
1 To 5



13: Wheel nsf
Scratched
Over 50mm

Interior

Carpet Condition -
Seat Condition -

Upholstery Condition -
Odour -

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK