



46 Brampton Road
Eastbourne
BN229BN

01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

MW70OSZ

Skoda Octavia 1.0 TSI e-TEC SE Technology 5dr DSG

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	13/01/2021	Body Style	Estate	CAP Clean	£15,250.00
Year	2021	Keys	2	CAP Average	£14,050.00
Mileage	9,922 Miles Warranted	Service history	Yes	CAP Below	£12,950.00
Fuel Type	Hybrid Electric	Last service date	08/01/2024	Gearbox	SEMI AUTO
Colour	BLUE	Last service miles	8,982	Gears	7
VIN	TMBKP7NX5MY073231	MOT Due	30/10/2025		

£65 ADDITIONAL FEE SERVICES CONFIRMED BY LOOKERS SKODA STOCKPORT Last service 08/01/2024 @ 8982 miles (2 MAIN DEALER SERVICES)

Tyres

NSF	GOODYEAR	3.0mm
NSR	GOODYEAR	4.0mm
OSF	GOODYEAR	4.0mm
OSR	GOODYEAR	4.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Trip computer
- USB/iPod interface
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- Drivers airbag
- Traction control
- Alloy wheels
- Cruise control
- Rear wiper
- Audio remote control
- Body coloured bumpers
- Climate control
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Front parking sensor
- Steering wheel mounted controls
- Auxiliary input socket
- Electric door mirrors
- Front armrest
- Rear electric windows
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- PAS
- Telephone
- Digital radio
- Roof rails
- Front electric windows
- Rear headrests
- ABS
- Side airbags
- Cloth seat trim

Photos






Condition Check



Damage Photos



1: Bumper Front
Chipped
Multiple Chips




2: Wing osf
Scratched
Over 25mm Not Thru Paint




3: Door osf
Chipped
1 To 5



4: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



5: Bumper Rear
Scratched
Over 25mm Not Thru Paint



6: Door nsf
Scratched
Over 25mm Not Thru Paint



7: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition OK
Seat Condition OK

Upholstery Condition OK
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK