



46 Brampton Road  
Eastbourne  
BN229BN

01323 520295 | no-reply@ebca.co.uk

# VEHICLE INSPECTION REPORT

**CV70WBY**

## Ford Kuga 2.0 EcoBlue mHEV ST-Line 5dr

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

nama  
GRADE  
1

### Details

Reg. date	06/10/2020	Body Style	Hatchback	CAP Clean	£14,750.00
Year	2020	Keys	2	CAP Average	£13,450.00
Mileage	38,361 Miles Warranted	Service history	Yes	CAP Below	£12,150.00
Fuel Type	Diesel	Last service date	10/08/2024	Gearbox	MANUAL
Colour	SILVER	Last service miles	33,314	Gears	6
VIN	WF0FXXWPMFLC62314	MOT Due	05/10/2025	Doors	5

£65 ADDITIONAL FEE Last service 10/08/2024 @ 33314 miles (2 MAIN DEALER SERVICES)

### Tyres


NSF	CONTINENTAL	5.0mm
NSR	CONTINENTAL	6.0mm
OSF	CONTINENTAL	5.0mm
OSR	CONTINENTAL	6.0mm
Spare		

## Features


- Bluetooth connection
- PAS
- Radio/CD
- Climate control
- Rear headrests
- ESP
- Central locking
- Alloy wheels
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Passenger airbag
- Remote central locking
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Traction control
- Cloth seat trim
- Navigation system
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Tyre pressure monitor
- Leather seat trim

## Photos





Condition Check



Damage Photos



1: Bumper Front  
Chipped  
1 To 5

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK