



VEHICLE INSPECTION REPORT

WJ13ZHH

Citroen C1 1.0i Connexion 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	30/05/2013	Keys	2	CAP Clean	£1,525.00
Year	2013	Service history	Yes	CAP Average	£1,125.00
Mileage	50,087 Miles Warranted	Service documents	Service Book	CAP Below	£725.00
Fuel Type	Petrol	Number of stamps	8	Gearbox	MANUAL
Colour	GREY	Last service date	01/05/2024	Gears	5
VIN	VF7PNCFB4CR540074	Last service miles	45,318	Doors	5
Body Style	Hatchback	MOT Due	27/05/2026		

£65 ADDITIONAL FEE.

Last service 01/05/2024 at 45,318 miles- 8 services

Tyres


NSF	COOPER TIRES	5.0mm
NSR	COOPER TIRES	5.0mm
OSF	LAUFENN	2.0mm
OSR	COOPER TIRES	5.0mm
Spare		

Features


- PAS
- Air conditioning
- Rear headrests
- Drivers airbag
- Central locking
- Rear wiper
- Folding rear seats
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Radio/CD
- Front electric windows
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Body coloured bumpers
- Front head restraints
- ABS
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bumper Front
Insecure
Action Required



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Door nsf
Dented
Over 30mm



5: Door nsr
Dented
Between 10mm + 30mm



6: Door osr
Scratched
Over 25mm Thru Paint



7: Door osf
Scratched
Up To 25mm Thru Paint



8: Wheel osf
Scratched
Up To 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK