



VEHICLE INSPECTION REPORT

GH18LHV

Suzuki Vitara 1.6 SZ-T 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	29/03/2018	Keys	2	CAP Clean	£6,600.00
Year	2018	Service history	Yes	CAP Average	£5,750.00
Mileage	74,641 Miles Warranted	Service documents	Service Book	CAP Below	£4,900.00
Fuel Type	Petrol	Number of stamps	8	Gearbox	MANUAL
Colour	TURQUOISE	Last service date	14/03/2025	Gears	5
VIN	TSMLYD21S00453550	Last service miles	73,649	Doors	5
Body Style	Hatchback	MOT Due	28/03/2026		

£65 ADDITIONAL FEE Last service 14/03/2025 @ 73649 miles (8 SERVICES (3 MAIN DEALER))

Tyres



NSF	FALKEN	5.0mm
NSR	FALKEN	5.0mm
OSF	FALKEN	5.0mm
OSR	FALKEN	5.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Body coloured bumpers
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Cruise control
- Rear wiper
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Central locking
- Navigation system
- Telephone
- Air conditioning
- Rear headrests
- Passenger airbag
- Remote central locking
- Park assist camera
- Radio/CD
- Climate control
- Metallic Paint
- Traction control
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Carpets Front
Torn
Between 3mm + 10mm



2: Wing osf
Dented
Over 30mm



3: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



4: Door osr
Dented
2 Or Less UpTo 10mm



5: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



6: Bumper Front
Chipped
1 To 5



7: Bonnet
Chipped
1 To 5



8: Screen Front
Chipped
UpTo 10mm



9: Bonnet
Dented
Between 10mm + 30mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
 Additional fees may apply to some vendors.
 Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK