



VEHICLE INSPECTION REPORT

HY65HTU

Toyota Yaris 1.33 VVT-i Icon 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	30/09/2015	Keys	2	CAP Clean	£4,625.00
Year	2015	Service history	Yes	CAP Average	£3,975.00
Mileage	60,797 Miles Warranted	Service documents	Service Book	CAP Below	£3,300.00
Fuel Type	Petrol	Number of stamps	10	Gearbox	MANUAL
Colour	GREY	Last service date	10/04/2025	Gears	6
VIN	VNKKJ3D350A317219	Last service miles	59,688	Doors	5
Body Style	Hatchback	MOT Due	21/04/2026		

Last Service - 10.04.2025 at 59688 miles (10 services 6 main dealer services) Headlight clouded

Tyres

NSF	BUDGET	4.0mm
NSR	RAPID	5.0mm
OSF	FULLRUN	5.0mm
OSR	BUDGET	6.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- 3x3 point rear seat belts
- ESP
- Side airbags
- Alloy wheels
- Park assist camera
- Digital radio
- Air conditioning
- Height adjustable drivers seat
- ABS
- Isofix child seat anchor points
- Central locking
- PAS
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- Curtain airbags
- Passenger airbag
- Remote central locking
- Rear wiper
- Electric door mirrors
- Front electric windows
- Metallic Paint
- Drivers airbag
- Rear airbags
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bumper Front
Scratched
25 to 100mm Thru Paint



2: Wheel nsf
Scratched
Over 50mm

No Image



3: Wing nsf
Scratched
Over 25mm Not Thru Paint

4: Door nsf
Scratched
UpTo 25mm Thru Paint



5: Door nsr
Scratched
Over 25mm Thru Paint



6: Wheel nsr
Scratched
Up To 50mm



7: Qtr Panel nsr
Chipped
1 To 5



8: Bumper Rear
Cracked
Over 25mm



9: Wheel osr
Scratched
Up To 50mm



10: Door osr
Chipped
1 To 5



11: Door osf
Chipped
Edge Chip



12: Wheel osf
Scratched
Up To 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK