

# VEHICLE INSPECTION REPORT

**RA12UVE**

## Nissan Juke 1.6 Tekna 5dr CVT

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**3**

### Details

Reg. date	23/05/2012	Keys	2	CAP Clean	£3,525.00
Year	2012	Service history	Yes	CAP Average	£3,025.00
Mileage	52,749 Miles Warranted	Service documents	Service Book	CAP Below	£2,500.00
Fuel Type	Petrol	Number of stamps	9	Gearbox	CVT
Colour	BLUE	Last service date	23/12/2024	Gears	1
VIN	SJNFBAF15U6226569	Last service miles	51,645	Doors	5
Body Style	Hatchback	MOT Due	03/01/2026		

Last Service - 23.12.2024 at 51645 miles (9 services) Gearbox fault

### Tyres


NSF	FALKEN	5.0mm
NSR	BUDGET	Damaged
OSF	FALKEN	5.0mm
OSR	BUDGET	4.0mm
Spare		

## Features


- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Metallic Paint
- ESP
- Central locking
- Cruise control
- PAS
- Digital radio
- Air conditioning
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Rear electric windows
- ABS
- Passenger airbag
- Leather seat trim
- Navigation system
- Rear wiper
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Side airbags
- Alloy wheels

## Photos





## Condition Check



## Damage Photos



1: Tyre nsr  
Damaged  
Replace



2: Bonnet  
Chipped  
1 To 5



3: Bumper Front  
Scratched  
25 to 100mm Thru Paint



4: Wheel nsf  
Scratched  
Over 50mm



5: Wing nsf  
Scratched  
Over 25mm Thru Paint



6: Door nsf  
Dented  
Over 30mm



7: Door nsr  
Dented  
Between 10mm + 30mm



8: Wheel nsr  
Scratched  
Over 50mm



9: Qtr Panel osr  
Scratched  
UpTo 25mm Thru Paint



10: Door osr  
Scratched  
Over 25mm Thru Paint



11: Door osf  
Scratched  
Over 25mm Thru Paint



12: Wheel osf  
Scratched  
Over 50mm



13: Roof  
Chipped  
1 To 5

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	Fault
Brakes	OK	Clutch Slip Test from Static	Fault
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	Fault
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK