



VEHICLE INSPECTION REPORT

MM15HXL

Ford Fiesta 1.0 EcoBoost 125 Titanium 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	18/06/2015	Keys	2	CAP Clean	£2,800.00
Year	2015	Service history	Yes	CAP Average	£2,325.00
Mileage	63,706 Miles Warranted	Service documents	Service Book	CAP Below	£1,825.00
Fuel Type	Petrol	Number of stamps	4	Gearbox	MANUAL
Colour	BLUE	Last service date	18/11/2022	Gears	5
VIN	WF0DXXGAKDFL43961	Last service miles	31,314	Doors	5
Body Style	Hatchback	MOT Due	14/07/2026		

Vehicle Recorded As INSURANCE THEFT On Condition Alert Register
Last service 18/11/2022 at 31,314 miles- 4 services

Tyres


NSF	AUTOGREEN	5.0mm
NSR	BUDGET	5.0mm
OSF	AUTOGREEN	5.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front electric windows
- Metallic Paint
- ESP
- Remote central locking
- Cruise control
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Cloth seat trim
- PAS
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- ABS
- Passenger airbag
- Alloy wheels
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Scratched
UpTo 25mm Thru Paint



2: Bumper Front
Scratched
UpTo 25mm Thru Paint



3: Wing nsf
Scratched
UpTo 25mm Thru Paint



4: Door nsf
Scratched
Over 25mm Thru Paint



5: Door nsr
Scratched
UpTo 25mm Thru Paint



6: Bumper Rear
Scratched
25 to 100mm Thru Paint



7: Roof
Dented
Over 30mm



8: Wheel osr
Scratched
Over 50mm



9: Qtr Panel osr
 Scratched
 UpTo 25mm Thru Paint



10: Door osr
 Chipped
 Edge Chip



11: Door osf
 Chipped
 Edge Chip



12: Wing osf
 Scratched
 UpTo 25mm Thru Paint

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK