



46 Brampton Road
Eastbourne
BN229BN

01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GY17KNC

Ford Fiesta 1.0 EcoBoost Zetec 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	29/04/2017	Keys	2	CAP Clean	£2,325.00
Year	2017	Service history	Yes	CAP Average	£1,850.00
Mileage	107,628 Miles Warranted	Service documents	Service Book	CAP Below	£1,375.00
Fuel Type	Petrol	Number of stamps	5	Gearbox	MANUAL
Colour	BLUE	Last service date	21/11/2024	Gears	5
VIN	WF0DXXGAKDHM14326	Last service miles	104,860	Doors	5
Body Style	Hatchback	MOT Due	07/08/2025		

Last Service -21.11.2024 at 104860 miles (5 services)

Engine Noisy/Tappy


Tyres

NSF	NEXEN	5.7mm
NSR	NEXEN	6.7mm
OSF	NEXEN	6.0mm
OSR	NEXEN	6.9mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Metallic Paint
- Passenger airbag
- Central locking
- Spare wheel
- Navigation system
- Telephone
- Air conditioning
- ABS
- Traction control
- Remote central locking
- PAS
- Radio/CD
- Front electric windows
- Drivers airbag
- Tyre pressure monitor
- Cloth seat trim
- Rear parking sensor
- Body coloured bumpers
- Rear headrests
- ESP
- Alarm
- Alloy wheels

Photos





Condition Check




Damage Photos




1: Wing osf
Poor Previous Repair
Poor Paint



2: Door osf
Chipped
Edge Chip



3: Qtr Panel osr
Poor Previous Repair
Poor Paint




4: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint




5: Door nsf
Chipped
1 To 5



6: Wing nsf
Dented
2 Or Less UpTo 10mm



7: Bonnet
Scratched
Over 25mm Not Thru Paint



8: A Post os
Poor Previous Repair
Poor Paint



9: B Post os
Poor Previous Repair
Poor Paint



10: C Post os
Poor Previous Repair
Poor Paint



11: Wheel nsf
Scratched
Up To 50mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK