



# VEHICLE INSPECTION REPORT

**GV66UAB**

## Volkswagen Polo 1.2 TSI Match Edition 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	13/02/2017	Keys	2	CAP Clean	£6,450.00
Year	2017	Service history	Yes	CAP Average	£5,625.00
Mileage	58,098 Miles Warranted	Service documents	Service Book	CAP Below	£4,825.00
Fuel Type	Petrol	Number of stamps	5	Gearbox	MANUAL
Colour	WHITE	Last service date	24/01/2024	Gears	5
VIN	WVWZZZ6RZHU038202	Last service miles	39,250	Doors	5
Body Style	Hatchback	MOT Due	12/02/2026		

£65 ADDITIONAL FEE

Last service 24/01/2024 at 39,250 miles- 5 services (1 main dealer)

### Tyres

NSF	RAPID	5.0mm
NSR	HIFLY	5.0mm
OSF	RAPID	5.0mm
OSR	HIFLY	5.0mm
Spare		

## Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Rear electric windows
- ABS
- Passenger airbag
- Cloth seat trim
- Cruise control
- Rear wiper
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Side airbags
- Alloy wheels
- Front parking sensor
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Metallic Paint
- ESP
- Central locking
- PAS
- Digital radio
- Air conditioning
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Front  
Chipped  
Multiple Chips





3: Wheel nsf  
Scratched  
Up To 50mm



4: Wing nsf  
Scratched  
Up To 25mm Thru Paint



5: Wheel osf  
Scratched  
Over 50mm



6: Door osf  
Chipped  
Edge Chip



7: Wheel osr  
Scratched  
Up To 50mm



8: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



9: Qtr Panel osr  
Scratched  
UpTo 25mm Thru Paint



10: Door nsf  
Chipped  
Edge Chip

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK