



VEHICLE INSPECTION REPORT

AG59JPJ

Volkswagen Polo 1.2 60 S 5dr [AC]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	04/02/2010	Body Style	Hatchback	Last service miles	42,434
Year	2010	Keys	1	MOT Due	06/06/2026
Mileage	72,361 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	5
Colour	GREY	Number of stamps	3	Doors	5
VIN	WVWZZZ6RZAU016843	Last service date	05/03/2015		

£100 ADDITIONAL FEE LAST SERVICE 5/3/15 @ 42,434 MILES (3 MAIN DEALER) PRINT Vibration from car when driving
Bonnet and nsf wing misaligned
High clutch

Tyres

NSF	BUDGET	5.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- PAS
- Electric door mirrors
- Front head restraints
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Cloth seat trim
- Rear wiper
- Air conditioning
- Height adjustable drivers seat
- ABS
- Passenger airbag
- Steel wheels
- Radio/CD
- Folding rear seats
- Rear headrests
- Drivers airbag
- Side airbags
- Body coloured bumpers
- Front electric windows
- Metallic Paint
- ESP
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Dented
Between 10mm + 30mm



2: Headlamps
Broken
Replace



3: Bumper Front
Poor Previous Repair
Paint Flake



4: Wing nsf
Dented
Over 30mm



5: Door nsf
Dented
Over 30mm



6: Sill ns
Dented
Between 10mm + 30mm



7: Door nsr
Scratched
Over 25mm Thru Paint



8: Qtr Panel nsr
Dented
With Paint Damage



9: Bumper Rear
 Scratched
 Over 100mm Thru Paint



10: Tailgate
 Dented
 Between 10mm + 30mm




11: Qtr Panel osr
 Dented
 Over 30mm



12: Door osr
 Dented
 Between 10mm + 30mm



13: Door osf
 Dented
 Over 30mm



14: Other
 N/A
 N/A



15: Seat Back Cover osr
Scuffed
Over 25mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	Fault
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK