



VEHICLE INSPECTION REPORT

GU16XOD

Toyota RAV4 2.0 V-matic Excel 5dr CVT

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
2

Details

Reg. date	31/03/2016	Body Style	Estate	MOT Due	30/03/2026
Year	2016	Keys	2	CAP Clean	£10,500.00
Mileage	71,776 Miles Warranted	Service history	Yes	CAP Average	£9,375.00
Fuel Type	Petrol	Service documents	Printout	CAP Below	£8,275.00
Colour	GREY	Last service date	14/03/2025	Gearbox	AUTOMATIC
VIN	JTMDEREV50D095403	Last service miles	71,292	Gears	1

Last service 14/03/2025 @ 71292 miles (5 SERVICES) Brakes squeaking

Tyres


NSF	BRIDGESTONE	6.0mm
NSR	BRIDGESTONE	5.0mm
OSF	BRIDGESTONE	6.0mm
OSR	BRIDGESTONE	5.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Auxiliary input socket
- Electric door mirrors
- Air conditioning
- Front electric windows
- Rear headrests
- ABS
- Isofix child seat anchor points
- Central locking
- Cruise control
- PAS
- Telephone
- Radio/CD
- Front fog lights
- Climate control
- Front head restraints
- Steering wheel rake adjustment
- Curtain airbags
- Passenger airbag
- Remote central locking
- Front parking sensor
- Rear parking sensor
- Trip computer
- USB/iPod interface
- Roof rails
- Electrically adjustable drivers seat
- Rear armrest
- Metallic Paint
- Drivers airbag
- Side airbags
- Leather seat trim
- Heated front seat
- Rear wiper
- Audio remote control
- Body coloured bumpers
- Space saver spare wheel
- Front armrest
- Rear electric windows
- 3x3 point rear seat belts
- ESP
- Traction control
- Alloy wheels

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5




2: Bumper Front
Scratched
Over 25mm Not Thru Paint



3: Wheel osf
Scratched
Over 50mm



4: Door osf
Chipped
1 To 5




5: Door osr
Scratched
Over 25mm Not Thru Paint



6: Wheel osr
Scratched
Up To 50mm



7: Bumper Rear
Chipped
Multiple Chips



8: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



9: Wheel nsr
Scratched
Up To 50mm



10: Door nsr
Chipped
1 To 5

No Image


No Image

11: Door nsf
Scratched
UpTo 25mm Not Thru Paint

12: Wing nsf
Scratched
Over 25mm Not Thru Paint



13: Wheel nsf
Scratched
Up To 50mm



14: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
-

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK